

JVC

SERVICE MANUAL

CD RECEIVER

KD-LX30R KD-LX10R



Supplyment

Areas suffix

E ----- Continental Europe

General assembly indication was wrong.
Please change the service manual of
KD-LX30R / KD-LX10R.
(Issue No.49551)

General assembly




■ **Parts list (General assembly)**


Block No. M1MM

⚠	Item	Parts number	Parts name	Q'ty	Description	Area
	112	QAR0029001-SA2	FEED MOTOR ASS'Y	1		
	113	PPN13KA10C-SA6	MOTOR ASS'Y	1		

Wrong



Collect



JVC

VICTOR COMPANY OF JAPAN, LIMITED
MOBILE ELECTRONICS DIVISION
PERSONAL & MOBILE NETWORK B.U. 10-1,1Chome,Ohwatari-machi,Maebashi-city,Japan