

# JVC

# SERVICE MANUAL


## CD RECEIVER

# KD-SH77R/KD-SH55R

**Supplement**

**Area Suffix**

E ..... Continental Europe  
EX ..... Central Europe



Difference point	DVD control	LINE IN	SUBWOOFER OUT	EXT OUT
KD-SH77R	O	O	O	O
KD-SH55R	X	X	X	X

The mistake was found in the logo of the cover.  
The logo display of CD-RW was deleted, and the logo of RDS was added.