

# JVC

# SERVICE MANUAL

## COLOR TELEVISION

**AV-36D501** (A US)  
**AV-36D201** (A US)


BASIC CHASSIS
GR2

Supplementary

The following item for the AV-36D501(A US), AV-36D201(A US) model were changed from those of the AV-36D501(US), AV-36D201(US) model.  
Therefore, this service manual describes only the items which differ from those of the AV-36D501(US), AV-36D201(US) service manual.  
For details other than those described in this manual, please refer to the AV-36D501(US), AV-36D201(US) service manual (No.51687, Feb. 2000).

## MAIN IDENTIFICATION

While referring to the illustration given below, identify model name on the rating label affixed to the rear cover.



## DIFFERENCE PARTS LIST

### EXPLODED VIEW PARTS LIST (Page36)

△	Ref. No.	Parts Number		Parts Name	Remarks
		AV-36D501(US) AV-36D201(US) (No.51687)	AV-36D501 (A US) AV-36D201 (A US) (No.51687B)		
△	V01	A90AEJ15X01	A90AHH50X10/V/	PICTURE TUBE	Not Interchangeable(Page36)
	101	LC20409-001B-A	LC20409-001C-A	DOOR	↑ (Page36)
		SGR-3003A-M2	SGR-3004A-M2	CRT SOCKET PWB	↑ (Page42)

● MAIN PWB PARTS LIST (Page38-41)

△	Ref. No.	Parts Number		Parts Name	Remarks
		AV-36D501(US) (No.51687)	AV-36D501(A US) (No.51687B)		
		SGR-1021A-M2	SGR-1024A-M2		
	R1423	NRSA02J-393X	NRSA02J-473X	CHIP RESISTER	Not Interchangeable
	R1425	_____	NRSA02J-334X	M G RESISTER	Addition
	R1427	QRT029J-1R5	QRT029J-2R2	MF RESISTER	Not Interchangeable
	R1428	_____	QRE121J-220Y	C R	Addition
	R1434	QRT029J-181	QRL029J-221	O M RESISTER	Not Interchangeable
	R1557	QRA14CF-3301Y	NRZ0032-2941X	MF RESISTER	↑
	R1732	NRSA02J-224X	NRSA02J-474X	CHIP RESISTER	↑
	C1431	QFLC1HJ-563Z	QFLC2AJ-104Z	M CAP.	↑
	C1435	NCB21HK-103X	NCB21EK-683X	CHIP C CAP.	↑
	L1531	CE41663-00B	CE41029-00A	LINIARITY	↑
	D1951	_____	MTZJ7.5A-T2	ZENER DIODE	Addition

● MAIN PWB PARTS LIST (Page38-41)

△	Ref. No.	Parts Number		Parts Name	Remarks
		AV-36D201(US) (No.51687)	AV-36D201(A US) (No.51687B)		
		SGR-1021A-M2	SGR-1024A-M2		
	R1423	NRSA02J-393X	NRSA02J-473X	CHIP RESISTER	Not Interchangeable
	R1425	_____	NRSA02J-334X	M G RESISTER	Addition
	R1427	QRT029J-1R5	QRT029J-2R2	MF RESISTER	Not Interchangeable
	R1428	_____	QRE121J-220Y	C R	Addition
	R1434	QRT029J-181	QRL029J-221	O M RESISTER	Not Interchangeable
	R1557	QRA14CF-3301Y	NRZ0032-2941X	MF RESISTER	↑
	R1732	NRSA02J-224X	NRSA02J-474X	CHIP RESISTER	↑
	C1431	QFLC1HJ-563Z	QFLC2AJ-104Z	M CAP.	↑
	C1435	NCB21HK-103X	NCB21EK-683X	CHIP C CAP.	↑
	L1531	CE41663-00B	CE41029-00A	LINIARITY	↑
	D1951	_____	MTZJ7.5A-T2	ZENER DIODE	Addition
△	RY1901	QSK0083-001	QSK0084-001	RELAY	Not Interchangeable
△	RY1921	QSK0083-001	QSK0084-001	RELAY	↑

## JVC SERVICE & ENGINEERING COMPANY OF AMERICA

### DIVISION OF JVC AMERICAS CORP.

**Head office :** 1700 Valley Road, Wayne, New Jersey 07470 (973)315-5000  
**East Coast :** 10 New Maple Avenue, Pine Brook, New Jersey 07058 (973)396-1000  
**Midwest :** 705 Enterprise St. Aurora, Illinois 60504 (630)851-7855  
**West Coast :** 5665 Corporate Avenue, Cypress, California 90630 (714)229-8011  
**Southwest :** 10700 Hammerly, Suite 105, Houston, Texas 77043 (713)935-9331  
**Hawaii :** 2969 Mapunapuna Place, Honolulu, Hawaii 96819 (808)833-5828  
**Southeast :** 1500 Lakes Parkway, Lawrenceville, Georgia 30243 (770)339-2582

### JVC CANADA INC.

**Head office :** 21 Finchdene Square Scarborough, Ontario M1X 1A7 (416)293-1311  
**Vancouver :** 13040 Worster Court Richmond B.C. V6V 2B3 (604)270-1311

