



SERVICE MANUAL

COLOUR TELEVISION

AV-28BD5EKI / AV-28BD5EP / AV-28BD5EE AV-28BD5EKIS / AV-28BD5EPS / AV-28BD5EES

Supplementary

Since some details of the AV-28BD5EKI/EP/EE/EKIS/EPS/EES service manual (No.51709 Oct. 2000) were incorrect, we are informing you of these errors and of the correct descriptions.

1. CORRECTED ITEMS

USING PW BOARD & REMOTE CONTROLLER (Page1-13)

Model	AV-28BD5EKI AV-28BD5EKIS	AV-28BD5EP AV-28BD5EPS	AV-28BD5EE AV-28BD5EES
PB ASSY			
MAIN PWB (with CRT SOCKET PWB)	PTMPMSA0001J	←	PTMPMS0002J

■ELECTRICAL PARTS LIST (Page1-16~22)

△	SYMBOL No.	PARTS No.		PARTS NAME	DESCRIPTION
		INCORRECT	CORRECT		
	C408	CMYE2G304J	CMYE2G274J (400V 0.27μF)	C MYLAR	Misprint
	R331	RS01Y181J-	RD-2Z201J- (1/2W 200)	R CARBON FILM	Misprint
△	R920	RF01Y129JA	RF01Y249JA (1W 2.4 J A)	R FUSIBLE	Misprint
	R350	RN-4Z1201F	RN-4Z2001F (1/4W 2K)	R METAL FILM	Misprint
	R351	RN-4Z1201F	RN-4Z2001F (1/4W 2K)	R METAL FILM	Misprint
△	R398	RD-2Z828J-	RF01Y828JA (1W 0.82 J A)	R FUSIBLE	Misprint
	R855	RD-4Z335J-	RD-4Z225J- (1/4W 2.2M)	R CARBON FILM	Misprint



VICTOR COMPANY OF JAPAN, LIMITED
HOME AV NETWORK BUSINESS UNIT 1106 Heta, Iwai-city, Ibaraki-prefecture, 306-0698, Japan

Printed in Japan
VP 0011
M.S.