

KEW Windows for KEW3128

Installation Manual



This manual contains instructions how to install the software "KEW Windows for KEW3128" supplied with KEW3128.

1. Introduction

● Interface

This instrument is equipped with a USB interface.

Communication method : USB Ver1.1

Following can be done by USB communication.

* Downloading files in the internal memory of the instrument to a PC.

* Making settings for the instrument via a PC

* Displaying the measured results on a PC as graphs in real-time, and also saving the measured data at the same time.

● System Requirements

- OS (Operation System)
Windows2000/XP/Vista (CPU : Pentium III 800MHz or more)
- Memory
256Mbyte or more
- Display
1024 x 768 dots, 65536 colors or more
- HDD (Hard-disk space required)
100Mbyte or more
- .NET Framework (2.0 or more)

● Trademark


- Windows® is a registered trademark of Microsoft in the United States.
- Pentium is a registered trademark of Intel in the United States.

The latest software is available for download from our homepage.
<http://www.kew-ltd.co.jp>


2. Installation of "KEW Windows for KEW3128" Software

- (1) Followings shall be checked before installing the software.
 - To prepare your system to install this software, please close all open programs.
 - Be sure NOT to connect the instrument with a USB until install is completed.
 - Installation shall be done with Administrative right.
- (2) Insert the CD-ROM "KEW Windows for KEW3128" in your PC's CD-ROM Drive. Then, the installer sets up automatically. When it doesn't run automatically, double click the "KEWLauncher.exe".


Click "Next" when following window appears.



- (3) Read through and understand the License Agreement and click "I accept it...", and then click "Next".



- (4) Click "Next" after entering the user information and specifying an install destination.




- (5) Confirm the information on install, and then click "Install" to start installing.



- (6) Install is completed when the wizard finishes. Click "Finish".



- (7) The installation of "KEW Windows for KEW3128" starts when the "KEW Windows" is installed successfully.



- (8) Repeat above step (3) through (6) to install the "KEW Windows for KEW 3128".

How to un-install the PC Software:
Access to the "Control Panel" in the Start Menu at the lower left on the Windows screen, and double click on the "Add/Remove Programs" to remove the "KEW Windows" and "KEW Windows for KEW3128".

3. USB Driver Installation

3-1 USB Driver Installation

- (1) Connect one end of a USB cord to your PC.
- (2) After connecting them properly, following balloon appears and install starts.



* A balloon shown below appears after following steps (3) and (4) complete. Step (3) and (4) will be repeated twice.



- (3) Click "Install the software automatically (recommended)", and insert the "KEW Windows for KEW3128" CD-ROM in your PC's CD-ROM drive. Then click "Next".



In case that following window appears on Windows XP, click "Continue anyway". (It is an operation check, and no problem happens if install is continued.)




(4) Install is completed when the wizard finishes. Click "Finish".



3-2 USB Driver Un-installation

When install of the USB driver is interrupted and reinstall cannot be done, follow the procedure below and delete the existing driver, and then install it again.

- (1) Connect a PC and the instrument with a USB cord.
- (2) Click the "Control Panel" in the Start menu.
- (3) Click "System" in the Control panel.
- (4) Then click "Device Manager".
- (5) Right click on "MODEL 8212USB" in the USB Controller.
- (6) Click "Uninstall" to uninstall the USB driver.



- (7) Remove the USB cord connecting your PC and the instrument once, and connect them again.

(8) When "Found New Hardware" window appears, follow the procedures described at "USB Driver Installation" and install the driver.

4. Start of "KEW Windows for KEW3128"

Start the software by; 1) clicking the icon for "KEW Windows" on the desktop, or 2) clicking "Start" → "Program" → "KEW" → "KEW Windows".

Then the Main Window of "KEW Windows" appears. Select the "KEW3128" and click "Next" or double-click on the "KEW3128" to start the software. Clicking "Exit" or "x" box at the upper right of the window quits the program.



Further detailed information is given in the HELP.

MEMO

 **KYORITSU ELECTRICAL INSTRUMENTS WORKS, LTD.**

No.5-20,Nakane 2-chome, Meguro-ku,
Tokyo, 152-0031 Japan
Phone: +81-3-3723-0131
Fax: +81-3-3723-0152
Factory: Ehime

www.kew-ltd.co.jp