
List of changes made to Larson Davis 831-INT-ET SBC¹

831-INT-ET Version 2.312

November 2016

- Updated User Interface inside of G4
- Fixed bug connectivity

831-INT-ET Version 2.311

August 2016

- Improved Data File Downloading
- Improved connectivity with G4 and Site Manager
- Updated User Interface inside of G4

831-INT-ET Version 2.310

March 2016

- Added Weather Data to Streaming Requests
- JSON Data Request Streaming
- Default IP Address if no DHCP is present
- Improved Screen Grabber
- String updates for Settings and System Property Screens

831-INT-ET Version 2.308

November 2015

- Improved communication with 831

831-INT-ET Version 2.306

December 2014

- Improved connectivity and communication with meter.
- Provided all support necessary for new G4 functions.
- Fixed stability bug (TT 6302).

831-INT-ET Version 2.305

August 2014

- Added support for G4 and associated SDK.

831-INT-ET Version 2.213

September 2013

- Improved file download speed and reliability for impaired Internet connections. (5828)
- Communication with the Model 831 is more robust.

831-INT-ET Version 2.209

July 2013

- Added the functionality to upgrade the firmware remotely using SLM Utility-G3. (5792)
- Improved password functionality.
- Added Secure Socket Layer (SSL) communications.

¹ Note: Numbers in parenthesis such as "(3210)" are an internal tracking number.