



**WAVEJET 300 SERIES OSCILLOSCOPE
VERSION 4.08 RELEASE NOTES**

JANUARY 2008

Corrections:

- DTSTUP remote command error over GPIB affecting Flash ROM is corrected. All WaveJet models with GPIB must be updated to this version