



## Merlin II Version 2.51 Release Notes

This release contains the following components, which are necessary for Merlin II

Analyzer to function correctly with this release:

- CATC Merlin II Bus Engine Version 1.10
- CATC Merlin II Firmware Version 1.00

Updated the Company Ids list to include new entries from the Bluetooth SIG's list.

Fixed a timing issue that caused the system not to operate on some analyzer boxes.

Fixed the 'Recording Wizard' to show the correct number of devices that were found during inquiry.

Merlin II is now capable of decoding RFCOMM packets across Segmented L2CAPs.

In HID decoding, the GET\_PROTOCOL and the SET\_PROTOCOL modifiers (Report and Boot) are now decoded correctly.