Programs After Market Services (PAMS) Technical Documentation

SERVICE MANUAL

[NMP Part No.0275358]

TFE-2 SERIES WLL TERMINAL



Last Update TFE-2: 03/98

Technical Documentation

AMENDMENT RECORD SHEET

Amendment Number	Date	Inserted By	Comments

Page 2 Original 03/98

Technical Documentation

Foreword

TFE-2 SERIES PHONES SERVICE MANUAL OVERALL CONTENTS

TFE-2 Series Core Transceiver booklet comprising

Foreword

Chapter 1: General Information

Chapter 2: System Module

Chapter 3: Transceiver TFE-2 variants

Chapter 4: Service Software Instructions

Chapter 5: Tuning Instructions

Chapter 6: Service Accessories

Chapter 7: Troubleshooting Instructions

Chapter 8: Non-serviceable Accessories

Original 03/98 Page 3

TFE-2 PAMS

Foreword

Technical Documentation

IMPORTANT

This document is intended for use by qualified service personnel only.

Company Policy

Our policy is of continuous development; details of all technical modifications will be included with service bulletins.

While every endeavour has been made to ensure the accuracy of this document, some errors may exist. If any errors are found by the reader, NOKIA MOBILE PHONES Ltd should be notified in writing.

Please state:

Title of the Document + Issue Number/Date of publication

Latest Amendment Number (if applicable)

Page(s) and/or Figure(s) in error

Please send to: Nokia Mobile Phones Ltd

PAMS Technical Documentation

PO Box 86 24101 SALO Finland

Page 4 Original 03/98

Technical Documentation

Foreword

Warnings and Cautions

Please refer to the phone's user quide for instructions relating to operation, care and maintenance including important safety information. Note also the following:

Warnings:

- CARE MUST BE TAKEN ON INSTALLATION IN VEHICLES 1. FITTED WITH ELECTRONIC ENGINE MANAGEMENT SYSTEMS AND ANTI-SKID BRAKING SYSTEMS. UNDER CERTAIN FAULT CONDITIONS, EMITTED RF ENERGY CAN AFFECT THEIR OPERATION. IF NECESSARY, CONSULT THE VEHICLE DEALER/MANUFACTURER TO DETERMINE THE IMMUNITY OF VEHICLE ELECTRONIC SYSTEMS TO RF ENERGY.
- THE HANDPORTABLE TELEPHONE MUST NOT BE OPERATED 2. IN AREAS LIKELY TO CONTAIN POTENTIALLY EXPLOSIVE ATMOSPHERES EG PETROL STATIONS (SERVICE STATIONS), BLASTING AREAS ETC.
- OPERATION OF ANY RADIO TRANSMITTING EQUIPMENT. INCLUDING CELLULAR TELEPHONES, MAY INTERFERE WITH THE FUNCTIONALITY OF INADEQUATELY PROTECTED MEDICAL DEVICES. CONSULT A PHYSICIAN OR THE MANUFACTURER OF THE MEDICAL DEVICE IF YOU HAVE ANY QUESTIONS. OTHER ELECTRONIC EQUIPMENT MAY ALSO BE SUBJECT TO INTERFERENCE.

Cautions:

- Servicing and alignment must be undertaken by qualified personnel only.
- 2. Ensure all work is carried out at an anti-static workstation and that an anti-static wrist strap is worn.
- 3. Ensure solder, wire, or foreign matter does not enter the telephone as damage may result.
- 4. Use only approved components as specified in the parts list.
- Ensure all components, modules screws and insulators are 5. correctly re-fitted after servicing and alignment. Ensure all cables and wires are repositioned correctly.

Original 03/98 Page 5 TFE-2 PAMS

Foreword

Technical Documentation

This page intentionally left blank.

Page 6 Original 03/98