




**AXIAL LEAD SOLDERING KIT
PACE PART NUMBER 6030-0063
MANUAL NUMBER 5050-0092 REV. A**

This kit contains sufficient components to assemble and solder 10 1/4 Watt (small resistors), and 10 1/2 Watt (large resistors) to the included printed circuit board as shown below.

Packing Contents

Part No.	Description	Qty.
1200-0042	Printed Circuit Board, Single Sided	1
1179-0003	1/4 Watt Resistors	10
1179-0002	1/2 Watt Resistors	10



The 1/2 Watt resistors are assembled into the larger holes and pads, the 1/4 resistors into the smaller holes and pads. Components are mounted on the side of the board that has no pads or conductors.

Detailed soldering instructions are contained in Procedure Sheet 6.




**AXIAL LEAD SOLDERING KIT
PACE PART NUMBER 6030-0063
MANUAL NUMBER 5050-0092 REV. A**

This kit contains sufficient components to assemble and solder 10 1/4 Watt (small resistors), and 10 1/2 Watt (large resistors) to the included printed circuit board as shown below.

Packing Contents

Part No.	Description	Qty.
1200-0042	Printed Circuit Board, Single Sided	1
1179-0003	1/4 Watt Resistors	10
1179-0002	1/2 Watt Resistors	10



The 1/2 Watt resistors are assembled into the larger holes and pads, the 1/4 Watt resistors into the smaller holes and pads. Components are mounted on the side of the board that has no pads or conductors.

Detailed soldering instructions are contained in Procedure Sheet 6.