













<p>Light Box and AC Adaptor VFK1164LBX1</p>  <p>AC Adaptor for C-Movie can be used. (DC +6V) Either plug can be used.</p> <p>(AC Adaptor is not supplied)</p>	<p>Infinity Lens (with Focus Chart) VFK1164TCM02</p> 		
<p>Post Height Adjustment Fixture LSVQ0021</p> 	<p>43mm Ring VFK1164TAR43</p>  <p>Camera Connecting Cable LSUP0017</p> 	<p>Color Conversion Filter (C14) VFK1164TFCT2</p>  <p>232C(M3) I/F Cable VFK1395</p> 	
<p>White Chart VFK1164TFWC2</p> 	<p>Color Bar Chart VFK1164TFCB2</p> 	<p>Gray Scale Chart VFK1164TFGS2</p> 	<p>Measuring Board for Electrical Adjustment VFK1308E</p> 
			<p>DC Output Cable and AC Adaptor VJA0941</p>  <p>(AC Adaptor is not supplied)</p>