

CHANGE IN RECORDER

From marking AH01 952 onwards recording/playback head and erase head are raised 0,2 mm in height.

Reason: Improved erase damping obtained by improved tape threading.

Note : Jig 4822 395 80152 (black) referred to in Service Manual is the one to be used for recorders manufactured as from marking AH01 952.
Earlier versions (before marking AH01 952) must be adjusted with jig 4822 395 80154 (transparent).

CHANGES IN DOCUMENTATION

- a) Under "Electrical measurements and adjustments", section 6.c. (page 11), text should read :
Curve c (Fig. 12) points to an excessive bias current and curve a is an indication of too small a bias current.
(Erroneously transposed in Service Manual).
- b) Fig. 3 (exploded view of cabinet) shows item no. 429 as a spring ring. This should however be the loose key of SK11 to SK16 (U303) (codenumber 4822 410 90047).