

Modification Kit

PHILIPS


S.O.P.S. (ES7062)

L6.1 - L6.2 AA CHASSIS

Position	Description	Qty
1501	Fuse 2.5Amp 250v	1
3514/3515	1R 5% 0.33w	2
6501	BZX79 B5v6	1
6502	BZX79 C15	1
6506	S1NB60	1
6514	BZT03-C200*	1
7502	BF423	1
7504	STP4N40FI	1

This service kit includes all the parts that may be damaged by breakdown of the S.O.P.S. powersupply. As mutual influences caused by the failure of one part are possible, in general all parts should be exchanged.

Warning: The use of non Philips components may lead to impaired performance and may result in damage to your TV.



Order Code..... P10663