

MODIFICATION KIT

PHILIPS MD1 CHASSIS SMPS (ES7056)

MD1.1E, MD1.2E, MD1.0A

Pos.	Description	MD1.1E 21"	MD1.1E >21"	MD1.2E 21"	MD1.2E >21"/20" WS	MD1.0A
1566	MP250 2.5A 65V	X	X	X	X	X
1572	2.5A 250V FUSE	X	X	X	X	X
1580	MP250 2.5A 65V	X	X	X	X	X
2525	220uF 25V 20%	X	X	X	X	
2525	470uF 35V 20%					X
3524	10R NFR25	X	X	X	X	X
6524	BYV10-20	X	X	X	X	X
6525	BYD33D	X	X	X	X	X
7520	MC44603P	X	X	X	X	X
7540	STP4NA60FI	X		X		
7541	STH8NA60FI		X		X	
7541	IRFPC60					X
7555	TL431CLP		X		X	X
7556	CNX82A	X	X	X	X	X

21" Adjust to an output voltage of $95v \pm 0.5v$ on TP9 by means of R3532.

>21" Adjust to an output voltage of $140v \pm 1v$ on TP9 by means of R3559.

This service kit includes all the parts that may be damaged by breakdown of the S.M.P.S. power supply. As mutual influences caused by the failure of one part are possible, in general all parts should be exchanged.

Order Code..... P32259

