
R197.115._80

Series : SMB CARLOCK

To obtain the complete P/N please fill in the blank "_" with the coding letter



All dimensions are in mm.

COMPONENTS	MATERIALS	PLATING	(µm)
		UL CLASSIFICATION	COLOR
HOUSING	PA6.6 GF15 (POLYAMIDE)	UL 94 V-2	See Page2

PACKAGING

Standard	Unit	Other
500	'W' option	Contact us

MECHANICAL CHARACTERISTICS

ENVIRONMENTAL

Mating life 100 Cycles mini Operating temperature -40/+110 ° C

Weight **1,6500** g


Issue: 0745 A

In the effort to improve our products, we reserve the right to make changes judged to be necessary.

RADIALL

R197.115._80

Series : SMB CARLOCK



UL CLASSIFICATION
UL 94V-2

-To obtain the complete P/N please fill in the blank "_" with the coding letter

CODING Z COLOR WATER BLUE

RAL 5021

Issue: 0745 A

In the effort to improve our products, we reserve the right to make changes judged to be necessary.

CODING K

COLOR CURRY RAL 1027




R197.115._80


Series : **SMB CARLOCK**


RECOMMENDED MOUNTING PROCEDURE



• Pre-insertion of the coax into the housing












• Push the connector into the housing until it clip on.









Issue: 0745 A

In the effort to improve our products, we reserve the right to make changes judged to be necessary.

RADIALL


R197.115._80


Series : **SMB CARLOCK**

RECOMMENDED DISASSEMBLING PROCEDURE



- To unlock the coax from the housing, rotate the coax until the tab is not in front of the elastic finger of the housing.
- insert a screw driver between the elastic finger and the slot of the housing as shown on the picture.
- Tip down the screw driver as shown on the picture to lift up the elastic finger until you have enough room.









- Hold on the elastic finger up and rotate the coax until the tab is in front of the elastic finger of the housing. (you can use the crimping of the jacket as a reference).
- pull on the cable assembly to remove the coax from the housing.







Issue: 0745 A

In the effort to improve our products, we reserve the right to make changes judged to be necessary

