

# RICOH

# Modification Bulletin

Model: AD330		Date: 28-Feb-97	No: 001	1/1
Modified Article: Duplex Unit Board			Prepared by: K. Ugaeri	
From: QAC 2nd Field Information Dept .			Checked by: S. Fujii	
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ( )	
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability		
	<input checked="" type="checkbox"/> Other			

To standardize the parts, the duplex unit board has been changed.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
G6945340	G6945350	Duplex Unit Board	1 - 1	x/o	2	5	

Model: AD330		Date: 31-Aug-97	No: 2
Modified Article: Parts catalog correction		Prepared by: M.Horiike	
From: QAC 2nd Field Information Dept.			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> To meet standards		
	<input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability                 (      )		
	<input type="checkbox"/> Part standardization <input type="checkbox"/> Other		

The following unit number for the Inverter Unit has been newly set up.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
-	G6944501	Inverter Unit	1	-	7	*	-

Please add this part number before Index No.1 on page 7 of your part s catalog.

This unit number includes all parts on page 7.

Model: AD330		Date: 15-Apr-98	No: 3
Modified Article: Mylar-Inverter Guide Plate		Prepared by: K.Ugaeri	
From: QAC Field Information Dept.			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	( )
	<input type="checkbox"/> Part standardization	<input type="checkbox"/> Other	

The following should be corrected. Please correct your part catalog.

The mylar is included in the inverter guide plate (G6944725, index no. 22, page 5).

