RIGOH

Modification Bulletin

Model: Bellini Printer Controller Type A Date			e: 27-Dec-00		No.: MB336001	
Modified Article: ROM DIMM			Prepared by: A. Sasaki			
From: Technical Se						
Reason for	□ Parts catalog correction	☐ Vendor ch	Vendor change		neet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability☐ Other		()	
	☐ Part standardization					

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B338 5700	ROM DIMM (Tool)	1		3	21	*1

*1: New index

PAGE: 1/1

Please add the above part to the parts catalog.

This is a service tool to be used when the printer controller firmware cannot be downloaded from a flash memory card.

Please refer to the service manual for the downloading procedure.