RIGOH

Modification **B**ulletin

PAGE: 1/1

Model: Model U-C1 Bypass Tray Date:			e:		No.: MB490001		
Modified Article: Bypass Feed Decal			Prepared	by: H.Ł	<.		
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To in	nprove	e reliability	()	
	☐ Part standardization	Othe	r				

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B0512580	B4902581	Bypass feed decal - English	1 - 1	X/O	3	13	
	B4902582	Bypass feed decal - German	0 - 1		3	13	
	B4902583	Bypass feed decal - Italian	0 - 1		3	13	
	B4902584	Bypass feed decal - French	0 - 1		3	13	
	B4902585	Bypass feed decal - Spanish	0 - 1		3	13	

Bypass Feed Decals in four languages have been added and the existing English decal has been modified to facilitate easier operation of the bypass tray. For details, please refer to RTB RB051010a.

Model	V/Hz	Destination	Code	Serial Number
Bypass Tray Type	120, 220, 230,	USA, Europe, Asia, etc	B490-17	J2837201658
1232	240/50, 60	-		

RIGOH

Modification Bulletin

PAGE: 1/1

Reissued: 12-Apr-05

Model: Model U-C1 By-pass Tray Unit	Date: 29-Mar-05	No.: MB490002a
-------------------------------------	-----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Motors, Metal pars, Harnesses			Prepared by: S. Tomoe		
From: 1st Tech. Support Sec. Service Support Dept.					
Reason for	☐ Parts catalog correction	☐ Vendor ch	ange	☐ To meet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	Other			

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G3045332	G3045333	Grounding Wire Harness	1-1	O/O	5	29	
B4905431	B4905432	By-pass Feed Harness	1-1	O/O	5	38	
G0602900	B1802900	Torque Limiter – 40mn.m 18mm	1-1	O/O	5	3	
G3046808	G3046825	Separator Guide Plate	1-1	O/O	5	5	
AF020543	AF020640	Driven Roller – By-pass Feed	1-1	O/O	5	7	
G0602937	B1802937	DC Solenoid – Pick-up	1-1	O/O	5	8	
B4906832	B4906833	Drive Bracket	1-1	O/O	5	9	
G3046829	G3046844	Tightener Arm	1-1	O/O	5	10	
AA140742	AA140771	Feed Shaft	1-1	O/O	5	16	
AA140741	AA140770	Drive Shaft	1-1	0/0	5	21	
G3046810	G3046827	Driven Shaft	1-1	0/0	5	22	
A2322862	B1542862	Driven Roller	1-1	0/0	5	40	

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

Model	V/Hz	Destination	Code	Serial Number
Bypass Tray Type		USA, Europe, Asia, etc	B490-17	J2856300160
1232	240/50, 60			

[<u>[</u>]	M	叮
	(0)	\prod

Modification **B**ulletin

etin	PAGE: 1/1
20 Mar 05	No : MD400003

Model: Model U-C1 By-pass Tray Unit Date			e: 29-Mar-05		No.: MB490003		
Modified Article: Sensors and Clutch					Prepared by: S. Tomoe		
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	☐ Parts catalog correction	☐ Vendor change ☐ To improve reliability		ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly			e reliability ()	
	☐ Part standardization	⊠ Othe	r				

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B4906835	B1546835	Rotary Switch – Paper Size Sensor	1-1	X/O	3	3	
AX200230	AX200260	Magnetic Clutch – 245 mn.m 35Z	1-1	X/O	5	15	
AW020056	AW020160	Photointerruptor	1-1	X/O	5	23	

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

Model	V/Hz	Destination	Code	Serial Number
Bypass Tray Type	120, 220, 230,	USA, Europe, Asia, etc	B490-17	J2856400300
1232	240/50, 60			

RIGOH

Reason for

Modification:

Model: Model U-C1 By-pass Tray Unit

Modified Article: By-pass Feed Table Cover

From: 1st Tech. Support Sec. Service Support Dept.

Modification Bulletin

	Date: 29-Mar-0			No.: MB490004		
		Prepared	by: S.	Tomoe		
t.						
☐ Vendor change			☐ To meet standards			
☐ To improve reliability			()		

PAGE: 1/1

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4906840	B4906862	Cover – By-pass Feed Table	1-1	X/O	3	11	

Change: The material for the bypass feed table was changed.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Reason: To increase the strength of the joints.

Model	V/Hz	Destination	Code	Serial Number	
Bypass Tray Type	120, 220, 230,	USA, Europe, Asia, etc	B490-17	J2856200001	
1232	240/50, 60				