Model: Mojito Copy Connector kit Type 700 Date			e: 06-Jun-0	0	No.: MB322001	
Modified Article: Interface Cable			Prepared by: M. Tsuyuki			
From: Technical Sei						
Reason for	☐ Parts catalog correction	☐ Vendor ch	ange			
Modification:	☐ To facilitate assembly	☐ To improv	e reliability	(UL)	
	☐ Part standardization	☐ Other				

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B3285050	B3225070	Interface Cable	1	X/X	3	6	
11050389	11050034	Clamp	2	X/X	3	106	

To meet UL standards, the interface cable has been changed. Therefore, the clamp also has been changed.

1. Copy Tray/Connector Kit Type 700

