

Model		ADF for F3/4					Volt/Hz	Date of Modification	Serial Number	
Modified Article		Separation Motor								
Reason for Modification		To ensure parts delivery and to facilitate service								
Draw No.	Old Parts No.	New Parts No.	Description	A.B.C.	Q'ty Used Old → New	Inter-changeability	Part needed for replacement by new part		Parts Catalog	
				Rank			Part No.	Description	Index No.	Page
	58865480		Separation Motor - DC21W		1 → 0				41	4 - 9
		58869500	Motor - DC21W Kit		0 → 1	O/O			41	4 - 9

Rank: A : Replace with new parts immediately. B : Replace with new parts at time of repair. C : Replace with new parts at time of overhaul.
 Interchangeability:
 (1) When old and new parts are not mutually interchangeable, use additional parts or an assembly part as indicated in "Parts needed for replacement by new part" to install the new part.
 (2) The mark to the left of the slash indicates whether the old part can be used in the new machine, and the mark to the right indicates whether the new part can be used in the old machine. x = Not interchangeable o = Interchangeable

DETAILS OF MODIFICATION

The separation motor modification was documented by MB No. 14 as follows:

Old P/N	New P/N	ICA	
#58865480			Separation Motor - DC21W
	#AX060027	X/X	Transport Drive Motor - DC21W
#58862202	#58862250	X/X	Pulley - 18T

The manufacturer no longer has a mold for the old motor (#58865480)

To ensure parts delivery and to facilitate service, the motor kit (#58869500), which is composed of the two new parts (#AX060027 and #58862250), is supplied as a spare part instead of the old motor (#58865480) .

T. Ito, Manager
Copier Technical Support

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
P.B. D305	115/60	U.S.A	5894-11	
SAVIN DF35	115/60	CANADA	5894-14	
SAVIN DF35	115/60	U.S.A., CANADA	5894-15	
RICOH DF32	115/60	U.S.A., CANADA	5894-17	— SERVICE PART ONLY
RICOH DF32	110/60	TAIWAN	5894-19	
NASHUA F456	220,240/60	EUROPE, etc.	5894-25	
INFOTEC ADF9035/DZ	220,240/50	EUROPE	5894-26	
RICOH DF32	220,240/50	EUROPE	5894-27	