

Model		ADF for P201/F9/F80					Volt/Hz	Date of Modification	Serial Number	
Modified Article		Separation Motor								
Reason for Modification		To ensure parts delivery and to facilitate service								
Draw No.	Old Parts No.	New Parts No.	Description	A.B.C.	Q'ty Used Old → New	Inter-changeability	Part needed for replacement by new part		Parts Catalog	
				Rank			Part No.	Description	Index No.	Page
	58865480		Separation Motor - DC21W		1 → 0			F9 P201 F80	5 5 5	1 - 55 9 - 7 5 - 7
		59189502	Motor - DC21W Kit		0 → 1	O/O		F9 P201 F80	5 5 5	1 - 55 9 - 7 5 - 7

Rank: A : Replace with new parts immediately. B : Replace with new parts at time of repair. C : Replace with new parts at time of overhaul.

Interchangeability:

(1) When old and new parts are not mutually interchangeable, use additional parts or an assembly part as indicated in "Parts needed for replacement by new part" to install the new part.

(2) The mark to the left of the slash indicates whether the old part can be used in the new machine, and the mark to the right indicates whether the new part can be used in the old machine. x = Not interchangeable o = Interchangeable

DETAILS OF MODIFICATION

The separation motor modification was documented by MB No. 14 as follows:

Old P/N	New P/N	ICA	
#58865480			Separation Motor - DC21W
	#59365501	X/X	Transport Drive Motor - DC21W
#59182292	#59182270	X/X	Pulley - 15T

The manufacturer no longer has a mold for the old motor (#58865480)

To ensure parts delivery and to facilitate service, the motor kit (#5189502), which is composed of the two new parts (#59365501 and #59182270), is supplied as a spare part instead of the old motor (#58865480).

T. Ito, Manager
Copier Technical Support

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
P.B. D206	115/60	USA, CANADA	5918-11	
SAVIN ADF for 7020	115/60	USA, CANADA	5918-15	
RICOH DF34	115/60	USA, CANADA	5918-17	— SERVICE PART ONLY
NASHUA F-513	220/50	EUROPE etc.	5918-25	
KALLE ADF for 9020Z/9032Z	220/50	EUROPE	5918-26	
RICOH DF34	220/50	EUROPE etc.	5918-27	