

Modification Bulletin

3 ulletin	PAGE: 1/1				
Date: 18-Nov-04	No.: MB603001				

Number Correction

Model: Model J-C1 Fax Unit

The bulletin number has been corrected. (MB149005→MB603001)

The ballouit hamber has been confederal (MBT 10000 7 MBC0000 1)							
Modified Article: P/N differences			Prepared by: H. Someya				
From: 1st Tech. Sup	port Sec. Service Support Dep	ot.					
Reason for	☐ Parts catalog correction	☐ Vendor change ☐ To improve reliability		☐ To meet standards			
Modification:	☐ To facilitate assembly			()			
	☐ Part standardization	Other					

The following are the P/N differences between the Asia model and Taiwan model of the J-C1 Fax Unit (B603).

Asia	Taiwan	Description	Q'ty	Int	Page	Index	Note
Model	Model						
G5702069	B5027180	Right Cover Keytop - Taiwan	1 - 1		3	15	
B6038608	B6038609	Operating Instructions FAX 1 - TWN	1 - 1		3	17	
B6038658	B6038659	Operating Instructions FAX 2 - TWN	1 - 1		3	17	

	JП
լեթլե)) ¦

Modification **B**ulletin

PAGE: 1	11
---------	----

Model: Model J-C1 Fax Unit Dat			Date	Date: 22-Nov-04		No.: MB603002	
Modified Article: P/N differences				Prepared by: H. Someya			
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	☐ Parts catalog correction	☐ Vendor change		ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		e reliability	()	
	☐ Part standardization	Othe	r				

The following are the P/N differences between the Asia model and China model of the J-C1 Fax Unit (B603).

Asia	China	Description	Q'ty	Int	Page	Index	Note
Model	Model	·					
G5702069	B6032071	Right Cover Keytop – CHN	1 - 1		3	15	
B6038608	B6038611	Operating Instructions FAX 1 - CHN	1 - 1		3	17	
B6038658	B6038661	Operating Instructions FAX 2 - CHN	1 - 1		3	17	