

Model	Menu Reader for F21/F22/F33/F34/A7/N440/F200	Volt/Hz	Date of Modification	Serial Number
Modified Article	Exterior Covers			
Reason for Modification	Due to NRG's request.			

The color of the exterior covers have been changed due to NRG's request.

Old P/N	New P/N	Description	Q'ty Used	Interchangeability	Parts Catalog	
					Index No.	Page
A9521029	A9521037	Upper Cover - LT	1 → 1	X/X	1	3
A9521003	A9521040	Indicator Decal - English	1 → 1	X/X	2 2	3 5
A9521112	A9521130	Menu Sheet Table	1 → 1	X/X	8	3
A9521213	A9521234	Lower Cover	1 → 1	X/X	18	3
A9521214	A9521235	Interface Harness	1 → 1	X/X	20	3
A9521216	A9521236	Shielding Plate	1 → 1	X/X	23	3
A9521031	A9521038	Upper Cover - A4	1 → 1	X/X	1	3
A9522001	A9522002	Indicator Decal - Mult.	1 → 1	X/X	2	3

T. Ito, Manager
Copier Technical Support

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
P.B. D967	115/60	USA	A952 - 11	-----
Savin Job Card System	115/60	USA	A952 - 15	-----
Nashua MR4965	115/60	Canada	A952 - 16	1232010001
Ricoh MR20	115/60	USA	A952 - 17	-----
Nashua MR4965	220, 240/50	Europe, etc.	A952 - 25	123208XXXX
HCS Program Unit 9165	220, 240/50	Europe	A952 - 26	-----
Ricoh MR20	220, 240/50	Europe, etc.	A952 - 27	-----
Minolta MR1	115/60	USA	A952 - 51	-----
Toshiba KP-1001	115/60	USA	A952 - 52	-----

Model	Menu Reader for F21/F22/F33/F34/A7/N440/F200	Volt/Hz	Date of Modification	Serial Number
Modified Article	Ferrite Core - TRCC - 23 - 11 - 14			
Reason for Modification	To meet the TÜV, standard.			

To meet the TÜV, the following part has been added in the accessory. This part is installed only when the menu reader is put on the F200 220 ~ 240V version.

Old P/N	New P/N	Description	Q'ty Used	Interchangeability	Parts Catalog	
					Index No.	Page
	16070430	Ferrite Core - TRCC - 23 - 11 - 14	0 → 1	-----	* 24	3

* New index

T. Ito, Manager
Copier Technical Support

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
P.B. D967	115/60	USA	A952 - 11	-----
Savin Job Card System	115/60	USA	A952 - 15	-----
Nashua MR4965	115/60	Canada	A952 - 16	-----
Ricoh MR20	115/60	USA	A952 - 17	-----
Nashua MR4965	220, 240/50	Europe, etc.	A952 - 25	123208XXXX
HCS Program Unit 9165	220, 240/50	Europe	A952 - 26	082XXXX
Ricoh MR20	220, 240/50	Europe, etc.	A952 - 27	2432030011
Minolta MR1	115/60	USA	A952 - 51	-----
Toshiba KP-1001	115/60	USA	A952 - 52	-----

Model	Menu Reader for F21/F22/F33/F34/A7/N440/F200	Volt/Hz	Date of Modification	Serial Number
Modified Article	Ferrite Core - TRCC - 23 - 11 - 14			
Reason for Modification	To improve electrical noise margin			

To improve electrical noise margin, the following part has been added in the accessory. This part is installed only when the menu reader is installed on the N440 and A7.

Old P/N	New P/N	Description	Q'ty Used	Interchangeability	Parts Catalog	
					Index No.	Page
-----	16070430	Ferrite Core - TRCC-23-11-14	0 → 1	-----	* 24	3

* New index

T. Ito, Manager
Copier Technical Support

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
P.B. D967	115/60	USA	A952 - 11	208XXXX
Savin Job Card System	115/60	USA	A952 - 15	314208XXXX
Nashua MR4965	115/60	Canada	A952 - 16	1232030001
Ricoh MR20	115/60	USA	A952 - 17	243208XXXX
Nashua MR4965	220, 240/50	Europe, etc.	A952 - 25	-----
HCS Program Unit 9165	220, 240/50	Europe	A952 - 26	-----
Ricoh MR20	220, 240/50	Europe, etc.	A952 - 27	-----
Minolta MR1	115/60	USA	A952 - 51	From First Production
Toshiba KP-1001	115/60	USA	A952 - 52	From First Production