RIGOH

Modification **B**ulletin

PAGE: 1/1

Model:Triton-C1 Pu	ate	te: 2-Aug-05		No.: MB734001			
Modified Article: Bracket / Stay				Prepared by: M. Tsuyuki			
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To m	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve reliabilit		e reliability	()	
	☐ Part standardization	☐ Other					

Change/Reason: The Parts Catalog was corrected as follows.

Old part	New part	Description	Q'ty	Int	Page	Index
number	number					
B7341116	B7341516	Catch Magnet (4407837720) Bracket (44210658000)	1	X/O	5	19
B7341134	B7341534	Bracket (44210016000) Bracket (6LE68046000)	1	X/O	5	28
B7341124	B7341524	Bracket (44210658000) Stay (6LE67300000)	1	X/O	5	30
B7341132	B7341532	Frame (44210658000) Frame (6LE68046000)	1	X/O	5	38



Modification Bulletin

PAGE: 1/1

Model: Triton-C1 Punch Unit (Hole Punch Unit Type 3131)			e: 10-Aug-0	5	No.: MB734002		
Modified Article: Bracket / Stay				Prepared by: M. Tsuyuki			
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	□ Parts catalog correction	☐ Vend	☐ Vendor change ☐ To improve reliability		☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To in			()	
	☐ Part standardization	Other					

Change/Reason: The Parts Catalog was corrected as follows.

Old part	New part	Description	Q'ty	Int	Page	Index
number	number					
B7341116	B7341516	Catch Magnet (4407837720) Bracket (44210658000)	1	X/O	5	19
B7341134	B7341534	Bracket (44210016000) Bracket (6LE68046000)	1	X/O	5	28
B7341124	B7341524	Bracket (44210658000) Stay (6LE67300000)	1	X/O	5	30
B7341132	B7341532	Frame (44210658000) Frame (6LE68046000)	1	X/O	5	38

