Model	1-bin Sorter	Volt/Hz	Date of Modification	Serial Number			
Modified Article		No serial number cut-in information					
Reason for Modification	Parts catalog correction						

The following should be corrected. Please correct your part catalog.

1. The following parts have been modified.

Old Part Number	New Part Number	Description	Q'ty	Index No.	Page	
AF022090	AF022098	Driven Roller	1	4	3	
A0493371	G0121531	Magnet	2	35	3	

for

S. Fujii, General Manager

2nd. Field Information Dept. QAC

RICOH

## Modification Bulletin

**PAGE: 1/1** 

Model: PT200		Date	e: 19-Mar-97	No: 2		
Modified Article: Bushing-6mm			Prepared by: K.Ugaeri			
From: QAC 2nd Field Information Dept.		Checked by: S. Fujii				
Reason for Modification:	☐ Parts catalog correction☐ To facilitate assembly☐ Part Standardization	☐ Vendor chai ☑ To improve ☐ Other		_ ,	meet standards )	

To reduce the noise from the 6mm Bushing, the material has been changed from January Production '97.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
Humber	Humber						
AA080220		Bushing-6mm	2-2	x/o	2	3	