

Model	2500LCT for F30/31, F33/34	Volt/Hz	Date of Modification	Serial Number
Modified Article	Fuse - 250V 2A			
Reason for Modification	Parts standardization			

To standardize parts with the other model, the fuse - 250V 2A has been changed. The interchangeability for each is O/O.

Old P/N	New P/N	Description	Q'ty	Index No.	Page
A4035502	11070509	Fuse - 250V 2A	1	19	5

T. Ito, Manager
Copier Technical Support

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
P.B. D745	115/60	USA, CANADA	A421 - 11	
SAVIN LCT9	115/60	USA, CANADA	A421 - 15	
NASHUA - 150	115/60	S. AMERICA etc.	A421 - 16	
RICOH RT21	115/60	USA, CANADA	A421 - 17	
NASHUA - 150	220, 240/50	EUROPE etc.	A421 - 25	
INFOTEC MAGAZIN 48	220, 240/50	EUROPE	A421 - 26	
RICOH RT21	220, 240/50	EUROPE etc.	A421 - 27	

Model	2500LCT for F30/31, F33/34	Volt/Hz	Date of Modification	Serial Number
Modified Article	Magnet Catch Ass'y			
Reason for Modification	Parts standardization			

To standardize with the other model, the magnet catch ass'y has been changed. The interchangeability for each is O/O.

Old P/N	New P/N	Description	Q'ty	Index	Page
50540536	AG070004	Magnet Catch Ass'y	1 → 1	44	5

T. Ito, Manager
Copier Technical Support

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
P.B. D745	115/60	USA, CANADA	A421 - 11	
SAVIN LCT9	115/60	USA, CANADA	A421 - 15	
NASHUA - 150	115/60	S. AMERICA etc.	A421 - 16	
RICOH RT21	115/60	USA, CANADA	A421 - 17	
NASHUA - 150	220, 240/50	EUROPE etc.	A421 - 25	
INFOTEC MAGAZIN 48	220, 240/50	EUROPE	A421 - 26	
RICOH RT21	220, 240/50	EUROPE etc.	A421 - 27	