

Model	J1 Auto Feeder	Volt/Hz	Date of Modification	Serial Number
Modified Article	Teflon Tape - 40 x 100			
Reason for Modification	Parts Catalog Correction			

Two teflon tapes are affixed to the inner guide plate. Its part number as an assembly is A4532845. However the part number of the tape is missing in the parts catalog. Therefore we registered the number of the tape as follows.

Page	Index	P/N	Description	Q'ty Used
5	73	A4532845	Inner Guide Plate	1
5	—	A4532847	Teflon Tape - 40 x 100	2

T. Ito, Manager
Copier Technical Support