Model: SP5/SP5L Printer Control Unit Date				e: 30-Nov-9	9	No.: MA852001	
Modified Article: Printer Control Board				Prepared by: A. Sasaki			
From: Technical Se							
Reason for	Parts catalog correction	☐ Vendor change		ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability			()	
	☐ Part standardization	Other					

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A852 5120—	T	Printer Controller	1		3	13	
	A852 5300	Printer Control Board Ass'y (Others)	1	X/O	3	13	
A852 5120 —	T	Printer Controller	1		3	13	
	^{LL} A852 5355	Printer Control Board Ass'y (Lanier)	1	X/O	3	13	

The old printer control board contains a blank flash ROM (no firmware).

So, it has been changed to an assembly that includes firmware in the flash ROM. The assembly consists of the parts as shown.

