-	пп
Œ0	101
11 16 111 1	l n l
1007007	

## Modification Bulletin

**PAGE: 1/1** 

Model: Model U-C1 500-sheet Finisher (SR830)			e: 2-Feb-04	No.: MB458001		
Modified Article: Main control Board Ass'y			Prepared by: Y.Urushihara			
From: 1st Tech. Support Sec. Service Support Dept.			]			
Reason for	☐ Parts catalog correction	☐ Vendor change ☐ To improve reliability		☐ To meet standards		
Modification:	☐ To facilitate assembly			( )		
☐ Part standardization ☐ Other						

The finisher PCB software has been modified so that,

- The jam condition is not triggered when the paper is pulled out of the finisher before the job is completed.
- Stapling is cancelled if the paper is removed from the finisher before stapling is done. Please correct your P/C as follows.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B4420450	B4580400	Main control Board Ass'y	1-1	X/O	13	14	

## **Japan Production**

MODEL NAME	DESTINATION	CODE	SERIAL NO.
SR830	All RICOH subsidiaries,	B458-17	J3830900590-608,798-848,886-
	NRG, SAVIN		960,968-969,973-990
SR830	Infotec	B458-26	6P81030001

വത്ത	叽
160	lnl

## Modification Bulletin

KUUUU Modificatio			<b>3</b> u	lletin		PAGE:	1/1
Model: Model U-C1 500-sheet Finisher (SR830)			Date	e: 26-Feb-0	4	No.: MB458002	
Modified Article: Main control Board Ass'y				Prepared by: Y.Urushihara			
From: 1st Tech. St	upport Sec. Service Support Dep	pt.					
Reason for	☐ Parts catalog correction			☐ To m	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve reliability		(	)		
	☐ Part standardization	☐ Other					

The following has been changed due to a vendor change.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B4580400	B4420460	Main Control Board Ass'y	1-1	O/O	13	14	