## RIGOH

Reason for

Modification:

## Modification Bulletin

☐ Other

Date: 29-Jun-08			5	No.: MB700001		
	Prepared by: H.Matsui					
pt.						
☐ Vendor change			☐ To meet standards			
☐ To improve reliability			(	)		

**PAGE: 1/1** 

Change: Callout #24 (B4686515 Support Tray) was added to the illustration.

Reason: It was missing from the Parts Catalog.

From: 2nd Tech. Support Sec. Service Support Dept.

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Model: Model V-C1 Finisher (SR970/980)

Modified Article: Parts Catalog

## **Exterior (B700/B701)**

