

<b>Model:</b> PRIPORT EG/EGLT		<b>Date:</b> 30-Sep-03	<b>No:</b> R-C607-001
<b>Subject:</b> EarlGrey-LT firmware history		<b>Prepared by:</b> A. Yoshida, Priport Service Planning Section	
<b>Classification:</b>	<input type="checkbox"/> Troubleshooting	<input checked="" type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Other (      )		
<b>Model Name:</b>			
EG (EarlGrey):            Printer unit type 80 RCP80			
EGLT (EarlGrey-LT):    Printer unit type 40 RCP40			

Note that this issue is related to the EarlGrey-LT only.

The following is the firmware modification history of Priport product EarlGrey-LT.

### FIRMWARE MODIFICATION HISTORY

Firmware Version	File Name	C.SUM	Production
1.1.7	C6245111D.bin	17AD	From the start of mass-production

**Model:** PRIPORT EG/EGLT**Date:** 30-Sep-03**No:** R-C607-001

<b>Symptom Corrected / Changes</b>	<b>Version</b>
First mass production release.	1.1.7

<b>Model:</b> PRIPORT EG/EGLT		<b>Date:</b> 5-Nov-03	<b>No:</b> R-C607-002
<b>Subject:</b> ROM History (Network Interface Board)		<b>Prepared by:</b> M. Ohtsubo, Priport Service Planning Section	
<b>Classification:</b>	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input checked="" type="checkbox"/> Retrofit information
	<input type="checkbox"/> Other (      )		
<b>Model Name:</b> EG (EarlGrey):            Printer unit type 80 RCP80 EGLT (EarlGrey-LT):    Printer unit type 40 RCP40			

This RTB details the firmware history for the Eland 99 (Network Interface Board).

The software versions listed below can be used for the NIBs on the following models:

Product Name	Product Code for Controller
EG (EarlGrey)	C607
EGLT (EarlGrey-LT)	C624

## FIRMWARE MODIFICATION HISTORY

Firmware Version	File Name	C. SUM	Production
4.1.0	G6785839P.bin	F0A3	From the start of mass-production

**Model:** PRIPORT EG/EGLT**Date:** 5-Nov-03**No:** R-C607-002

<b>Symptom Corrected / Changes</b>	<b>Version</b>
First mass production release.	4.1.0

<b>Model:</b> PRIPORT EG/EGLT		<b>Date:</b> 5-Nov-03	<b>No:</b> R-C607-003
<b>Subject:</b> EarlGrey firmware history		<b>Prepared by:</b> M. Ohtsubo, Priport Service Planning Section	
<b>Classification:</b>	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input checked="" type="checkbox"/> Retrofit information
	<input type="checkbox"/> Other (        )		
<b>Model Name:</b> EG (EarlGrey):            Printer unit type 80 RCP80 EGLT (EarlGrey-LT):    Printer unit type 40 RCP40			

This RTB details the system firmware history for the EG (EarlGrey).

**FIRMWARE MODIFICATION HISTORY**

Firmware Version	File Name	C. SUM	Production
1.3.0	C6075131E.bin	7ECD	F162040024
1.2.5	C6075131C.bin	959E	From the start of mass-production

**Model:** PRIPORT EG/EGLT**Date:** 5-Nov-03**No:** R-C607-003

<b>Symptom Corrected / Changes</b>	<b>Version</b>
<b>(Modified for use on the Japan model)</b>	<b>1.3.0</b>
First mass production release.	1.2.5