



SERVICE BULLETIN

PRODUCT: Computer Monitor
BULLETIN: MON00-001
MODEL: CSE7839, CSE9839,

SUBJECT: Decrease the Failure Rate of Q501

BACKGROUND: Allow a sufficient margin between the Drain and Source of Q501

SOLUTION: Change the capacitance of C501 from 50V/47uF to 100V/10uF.

PARTS LIST: See Below

ORIGINAL			NEW	
Location No.	Part No.	Description	Part No.	Description
C501	2401-001585	C-ELEC. 50V/47uF 105	2401-000393	C-ELEC. 100V/10uF 105

Disclaimer: This information is provided "as is" without warranty of any kind either expressed or implied, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose.