



SERVICE BULLETIN

Product: 17" LCD MONITOR
Model: CN17VSSN
 SyncMaster 760V

Bulletin No.: MON01-005 (01-C/M-E0036)
Bulletin Date: August 29, 2001
ECN Date: MAY 2001

SUBJECT: LCD Panel Change

Background: Early production of the SyncMaster 760V used a Unipac manufactured LCD panel. This panel has been changed to one manufactured by ADT. When replacing the Unipac panel with the ADT, the unit panel bracket should be replaced as well.

Cause: Unipac was replaced with ADT to improve image quality.

Solution: Replace the panel and panel bracket when replacing defective Unipac panels with ADT panels.

Application Date: May 2001

ORIGINAL			NEW	
Location No.	Part No.	Description	Part No.	Description
LCD PANEL	BN07-00028A	Unipac panel	BN07-00044A	ADT Panel
BRKT-PANEL BRKT-FRONT	BN70-10039A BN75-00009A	BRKT-PANEL REAR LSA710 UNIT/BRKT-FRONT	BN75-00128B	UNIT-BRKT PANEL