



# SERVICE BULLETIN

**Product:** CRT MONITOR  
**Model:** PG22NS  
(SyncMaster 1200NF)

**Bulletin No.:** MON02-008 (02-C/M-E0079)  
**Bulletin Date:** August 26, 2002  
**ECN Date:** August 21, 2002

**SUBJECT:** Sync Problem

**Background:** When applying 31K/60HZ or 31K/70HZ input signals to the monitor as it heats up, the signal goes off frequency and becomes un-synchronized.

**Cause:** Insufficient thermal characteristic of capacitor CS216.

**Solution:** Change the characteristics of capacitor CS216.

**Application Date:** August 21, 2002

ORIGINAL			NEW	
Location No.	Part No.	Description	Part No.	Description
CS216	2201-000863	C-CERAMIC, DISC, 0.68nF,10%,50V	2202-000003	C-CERAMIC, MLC-RADIAL; 680pF, 2%, 100V