

Product : TFT-LCD 240T(PC24PB*)	Bulletin No. : 00-C/M-E0017
Model : TFT-LCD 240T(PC24PB*)	Bulletin Date : 21. Mar. 2001
Buyer : All subsidiaries	ECN Date : 04. Jan. 2001
SUBJECT : Adapter Problem with 240T TFT-LCD	

Symptoms : No Power.

Cause : In case of the older Adator can be possible to occur a failure because the R103 of PFC circuit has a weak about the surge voltage.

Solution : In case of the 240T monitor which was produced before Dec.2000,Change with a new adapter.

Application Date : At once

(Interchangeability Code : * I.C)

Location No.	OLD (before) Parts		NEW (changed) Parts		* I.C
	SEC Code	Description	SEC Code	Description	
Adapter	BN44-00043A	100-240Vac,47-63HZ	BN94-00018K	PC24PSA,AC110/240V,DC14V/6A	C

Type	A type	B type	C type	D type	E type	F type
Interchange Type Code (* I.C)	OLD → Early (Parts) (Prod.) NEW → Late	OLD → Early (Parts) (Prod.) NEW → Late	OLD → Early (Parts) (Prod.) NEW → Late	OLD → Early (Parts) (Prod.) NEW → Late	Parts Addition (None New)	Parts deletion (Old Del.)
Application	Reference () Only Defected sets () Whole sets ()					
Attachment	Schematic Diagram () Component Lay-out () Exploded View () Mechanical Diagram () None () Others (0)					

Product Month : 2000, Sep ~ Dec	Serial No. (~ from)	
Published by : C.K.Park	Checked by : C. K.Park	Approved by : J.U.Lee