



SERVICE BULLETIN

Product : S/M760V LCD monitor (CN17VS)	Bulletin No. : 01-C/M-E0036
Model : S/M760V	Bulletin Date : August.27,2001
	ECN Date : May,2001
SUBJECT : LCD panel change	

Background : Some S/M760V LCD model used Unipac LCD panel.
 This panel changed to ADT panel for better quality.
 And Samsung provides ADT panel for service parts.
 When replacing Unipac with ADT panel, braket panel should be replaced at a same time

Model name : S/M170T

Solution Replace panel and panel braket when replacing defected unipac panel and ADT panel

Application Date : May,2001

(Interchangeability Code : * I.C)

Location No.	OLD (before) Parts		NEW (changed) Parts		* I.C	
	SEC Code	Description	SEC Code	Description		
Panel	BN07-00028A	Unipac panel	BN07-00044A	ADT Panel	C	
BRKT-PANEL BRKT-FRONT	BN70-10039A BN75-00009A	BRKT-PANEL REAR LSA710 UNIT/BRKT-FRONT	UNIT-BRKT PANEL	BN75-00128B		
Type	A type	B type	C type	D type	E type	F type
Interchange Type Code (* I.C)	OLD → Early (Parts) (Prod.) NEW → Late	OLD → Early (Parts) (Prod.) NEW → Late	OLD → Early (Parts) (Prod.) NEW → Late	OLD → Early (Parts) (Prod.) NEW → Late	Parts Addition (None New)	Parts deletion (Old Del.)
Application	Reference () Only Defected sets (<input type="radio"/>) Whole sets (<input type="radio"/>)					
Attachment	Schematic Diagram (<input type="checkbox"/>) Component Lay-out (<input type="checkbox"/>) Exploded View (<input type="checkbox"/>) Mechanical Diagram (<input type="checkbox"/>) None (0) Others (<input type="checkbox"/>)					
Product Month : - Auall	Serial No. (~ from)					
Published by : C.J.Oh	Checked by : C. K.Park		Approved by : Y.K.Yoo			

