

Product : CRT Monitor

Bulletin No. : 02-C/M-E0092

Model : PN17L,AQ17L,AN17L

Buyer :

Bulletin Date : 30.Oct,2002

SUBJECT : Q404 change for quality improvement

Background : High defect ratio at Q404 of 17" CRT monitor.

Samsung changed Q404 horizontal output TR to reduce field defect as below.

* Before : KSC5802 or FJAF6810

* After : FJAF6910 (Has more good surge character than previous parts)

Solution : Use changed part(FJAF6910) in case of Q404 defect.(KSC5802,JFAF6810)

Samsung Application date (Factory)

- PN17L* : June,2002 ~

- AQ17L*,AN17L* : Nov,2002 ~

Location No.	OLD (before) Parts		NEW (changed) Parts	
	SEC Code	Description	SEC Code	Description
Q404	0502-001129	KSC5802,NPN,70000mW, TO-3PF,ST,20-40	0502-001218	FJAF6910,NPN,60000MW, TO-3PF,ST,7-10
Q404	0502-001217	FJAF6810,NPN,60000MW, TO-3PF,ST,5-8		

Application Reference () Only Defected sets (O) Whole sets ()

Attachment Schematic Diagram () None ()

Published by : C.J.Oh

Checked by : M.S.Park

Approved by : K.S.Yeo