

Product : Color monitor	Bulletin No. : 98-MON-E0002
Model : All Model	Bulletin Date : Feb. 23. 1998
Buyer : All subsidiaries	ECN Date : Feb. 20. 1998

SUBJECT : Information of New Macintosh Mac Master

Background : To apply New adapter (Macintosh Adapter Mac Master I I) which added separate Sync (Symptom) operation on the OLD adapter (Macintosh Adapter Mac master)

Cause :

Solution :

Application Date : January.1998

(Interchangeability Code : * I.C)

Location No.	OLD (before) Parts		NEW (changed) Parts		* I.C
	SEC Code	Description	SEC Code	Description	
-			3719-001073	Only SEA	
-			3719-001071	Other cuntry	

Type	A type	B type	C type	D type	E type	F type
Interchange Type Code (* I.C)	OLD → Early (Parts) (Prod.) NEW → Late	OLD → Early (Parts) (Prod.) NEW → Late	OLD → Early (Parts) (Prod.) NEW → Late	OLD → Early (Parts) (Prod.) NEW → Late	Parts Addition (None ꞑæ New)	Parts deletion (Old ꞑæ Del.)

Application Reference (O) Only Defected sets () Whole sets ()

Attachment Schematic Diagram () Component Lay-out () Exploded View ()
 Mechanical Diagram () None () Others (O)

Product Month : Jan. 1998

Serial No. (~ from)

Published by : G.M.Chung

Checked by : J. U.Lee

Approved by : B.W.KANG