



SERVICE BULLETIN

Bulletin #: DLP03-004

Subject: Squealing noise comes from set, near optical engine area.

Background: When set is turned on, optical engine color wheel will have a squealing noise from the motor bearing.

Solution: Replace color wheel. Part # BP96-00250A



Remove Cover

Remove Color Wheel