

SHARP

Technical Bulletin

FACSIMILE

Sharp Electronics Corporation
 Services and Support Group
 1300 Naperville Drive
 Romeoville, IL 60446

Number: FAX-227

Date: June 2000


Model(s): FO-77
 UX-44 / 66

Subject: Dislocation of Platen Bearing

Symptom: The Platen Bearing may dislocate from the frame when dropped or subjected to strong vibration.

Cause: The Platen Bearing shape.

Corrective Action: The Platen Bearing shape has been changed.



**PRODUCTION CUT IN DATE:
 MARCH 2000**

Item No.	Model	Current Part Code	New Part Code	Price Rank	Description	Inter-changeability
1	All listed	LBSHP2112XHZZ	LBSHP2112XHZA	AA	Platen Bearing	1
Interchangeability						
1. Interchangeable				4. Not interchangeable		
2. Current type can be used in place of new type. New type cannot be used in place of current type.				5. Interchangeable if replaced with same types of related parts in use.		
3. Current type cannot be used in place of the new type. New type can be used in place of current type.				6. Others.		