

## TELEVISION TECHNICAL BULLETIN

---

**MODELS**      28HW53H                      32HW53H

**REASON**      The part number for T702 (triac) is missing from the service manual

**ACTION**      Please add the following part number to your copy of the service manual T702

<b><u>REF NO</u></b>	<b><u>DESCRIPTION</u></b>	<b><u>PART NUMBER</u></b>	<b><u>PRICE CODE</u></b>
T702	Triac, BT134W-500	VHDBTW34F//-1	AE

---

**Sharp Electronics (UK) Limited**

Reference 20092002-1

Revision 1

White – Carry out as required

Yellow – Carry out as required and whenever the unit comes in for service

Red – Carry out on all units