

## TELEVISION TECHNICAL BULLETIN

**MODELS**      **51AT15H**

**SYMPTOM**    Teletext problems.

**CAUSE**        Changes in circuit tolerances affecting CBVS signal.

**ACTION**        Fit a 220nF capacitor in parallel with R521.

Use the part number given below for the capacitor.

<b><u>REF NO</u></b>	<b><u>DESCRIPTION</u></b>	<b><u>PART NUMBER</u></b>	<b><u>PRICE CODE</u></b>
-	Capacitor, 220nF	RC-FZ9224BMNJ	AD