

TELEVISION TECHNICAL BULLETIN

<u>MODELS</u>	51CS03H	51CS05H	59CS03H	59CS05H
	59CSD8H	66CS03H	66CS05H	66CSD8H

SYMPTOM After the set has warmed up, the AFT circuit may become unstable. This leads to the set drifting off tune, either on one channel or all channels.

CAUSE Changes of tolerances in the AFT circuit.

ACTION Readjust the AFT circuit as described in the adjustment service manual.

This is duplicated below for reference.

1. Place the set in the service mode.
2. Apply a colour bar pattern to the RF input at 855.25MHz.
3. Press the standby button on the remote control.
4. The set will now undertake the AFT adjustment automatically.
5. Turn the set off by the mains switch to cancel the service mode.