

TELEVISION TECHNICAL BULLETIN

MODELS 66GS62H

REASON Upgrade E/W transistor to improve reliability (Q602).
Change of Heatsink to reduce the operating temperature (Q601, Q602)

ACTION Change Q602 to RHTX0236BMZZ (2SK2843 600V Toshiba). Also replace the Heatsink of Q601/2 to PRDARA018WJFW (larger size) in order to reduce their operating temperature.

<u>REF NO</u>	<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>PRICE CODE</u>
Q602	TRT 2SK2843 Heat sink set	RHTX0236BMZZ PRDARA018WJFW	AE AC

Sharp Electronics (UK) Limited


Reference SP021700X

Revision 1

White – Carry out as required

Yellow – Carry out as required and whenever the unit comes in for service

Red – Carry out on all units



Sharp Electronics (UK) Limited

Reference SP021700X

Revision 1

White – Carry out as required

Yellow – Carry out as required and whenever the unit comes in for service

Red – Carry out on all units