

TELEVISION TECHNICAL BULLETIN

MODELS **DV5131H** **DV5150H**

REASON During production of the above models, the manufacturer of the chopper transformer (T701) has been changed.

This change has taken place from the following serial numbers.

DV5131H - 715610
DV5150H - 713410

The new transformer is now supplied as an alternative to the original.

ACTION When replacing T701 in sets before the serial numbers given above, carry out the following circuit change.

1. Replace R509 with a 2.2R 0.5W resistor.
2. Remove D502 and replace with a wire link.
3. Remove D503.

Use the part numbers given below.

<u>REF NO</u>	<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>PRICE CODE</u>
T701	Chopper Transformer	RTRNZ0511BMZZ	AV
R509	Resistor, 2.2R 0.5W	VRD-RA2HD2R2J	AA
D502	Jumper, 15mm	QJUM-2001CEFW	AA