

TELEVISION TECHNICAL BULLETIN

Subject: Alternative chopper transformer fitting instructions

MODELS DV5131 DV5150

SYMPTOM During production, the manufacturer of the chopper transformer, T701, was changed.

ACTION If chopper transformer, T701, RTRNZ0510BMZZ (current type manufactured by Eldor) has been fitted then ensure that R746 is 2.2Ω.

If chopper transformer, T701, RTRNZ0511BMZZ (alternative type manufactured by Diemen) has been fitted then ensure that R746 is 3.3Ω.

Use the part numbers given below.

Note that R746 is a safety resistor and the part number below must be used when replacing this item.

<u>REF NO</u>	<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>PRICE CODE</u>
T701	Chopper TX (alternative)	RTRNZ0511BMZZ	AV
T701	Chopper TX (current)	RTRNZ0510BMZZ	AV
R746	3.3Ω, ½W (alternative)	RR-XZ0206BMZZ	AB
R746	2.2Ω, ½W (current)	RR-XZ0204BMZZ	AB