

TELEVISION TECHNICAL BULLETIN

Subject : No sound

SYMPTOM No sound on either FM, Nicam or SCART.

CAUSE Incorrect data values stored within the NVM, IC104.

ACTION If the set contains a three chip Nicam PWB change the data within the NVM as follows :-

Location	0C	0D	0E	0F	10	11	12	13	14	15
Value	20	01	01	06	69	01	04	44	00	00
Location	16	17	18	19	1A	1B	1C	1D	1E	
Value	1F	00	00	0C	02	35	FF	FF	FF	

If the set contains a single chip Nicam PWB change the data within the NVM as follows :-

Location	0C	0D	0E	0F	10	11	12	13	14	15
Value	80	80	0C	28	23	14	28	24	5F	28
Location	16	17	18	19	1A	1B	1C	1D	1E	
Value	45	73	08	00	08	0A	0A	12	12	

Note

NVM location values are accessible from the service mode. Refer to the service manual for details on entering and changing data within the service mode.