

# SONY

## car stereo Service Bulletin No.71

Technical Department  
Sony Service Company  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-27R

Date: November 24, 1986

Subject: Part Number Correction -  
FADER CONTROL

**Symptom:**  
(\*\*)

The part number for the FADER CONTROL (RV-701) listed in the XR-27R/37R service manual is the one used in the XR-37R. The part number for the fader in the XR-27R is listed below: This part number should also be stamped on the fader control.

Ref. No.	Description	Part Number	
		Incorrect	Correct
RV-701	FADER CONTROL	1-237-124-11	1-230-735-11