

SONY

car stereo Service Bulletin No. 79

Technical Department
Sony Service Company
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-44

Date: June 26, 1987

Subject: Wrong Part Number - Capstan
E-Ring

Symptom:
(**)

The part number in the service manual for the E-Ring clip used on the capstans is incorrect. Note the correct part number below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
168	E-Ring	7-624-102-04	<u>3-590-768-00</u>

