

# SONY

## car stereo Service Bulletin No.83

Technical Department  
Sony Service Company  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-A10, CDX-R7, CDX-5, CDX-R88

Date: September 4, 1987

Subject: Replacement Part Numbers For  
Optical Assemblies

**Symptom:**  
(\*\*)

The part numbers for the optical block assemblies have been changed for better inventory control. The part itself has not been changed. The former part numbers are substituted in Kansas City Parts.

**Solution:**

Description	Former	New	Description	Former	New
KSS-100A	X-4884-531-1	8-848-001-01	KSS-110B	X-3320-529-1	8-848-013-01
BU-1C	X-4908-207-3	X-4908-206-1	KSS-110C	X-3320-104-1	8-848-022-01
KSS-123A	X-4913-720-1	8-848-056-01	KSS-110D	X-3320-112-1	8-848-037-01
KSS-122A	X-4910-444-1	8-848-055-01	KSS-110E	X-3329-540-1	8-848-038-01
KSS-124A	X-4917-526-1	8-848-077-01	KSS-110G	X-4912-409-1	8-848-039-01
BU-1E	X-4915-033-1	X-4915-032-1	KSS-150B	X-4919-917-1	8-848-078-01
KCS-100A (TAOHS)	X-4887-141-3	X-4887-143-1	KSS-160A	X-4917-716-1	8-848-066-01
KSS-150A	X-4917-051-1	8-848-062-01	KSS-160B	X-3320-570-1	8-848-067-01